



Telephone: 867-678-6676
Fax: 867-678-6699

November 7, 2018

Government of the Northwest Territories - Department of Transportation
PO Box 2038
Inuvik, NT X0E 0T0

Attention: Dean Ahmet

File Number N7L1-1835
Type of Operation CLASS A - INDUSTRIAL
Location

Dear Dean Ahmet,

An inspection of the above noted operation was conducted on November 06, 2018 by Water Resources Officer Lloyd Gruben .

Enclosed is a copy of the INDUSTRIAL Water Use Inspection Report.

If you have any questions, please contact me at 867-678-6676.

Sincerely,

Lloyd Gruben
Water Resources Officer
Environment and Natural Resources
Beaufort Delta

Cc:

Norman Snowshoe – Regional Superintendent ENR
Mardy SEMmler – Executive Director – Inuvialuit Water Board
Bijaya Adhikara – Science and Regularory Coordinator
Freda Wilson – Inuvialuit Water Board



«INSP_TYPE» WATER USE INSPECTION REPORT

| | | | |
|---------------------|---|-----------------------------|--------------------------|
| LICENCE #: | N7L1-1835 | EXPIRY DATE: | December 11, 2023 |
| LICENCEE: | Government of the Northwest Territories - Department of Transportation | PREVIOUS INSPECTION: | November 22, 2017 |
| COMPANY REP: | Dean Ahmet | INSPECTION DATE: | November 06, 2018 |

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

| | | | | | |
|-------------------------|-----|---------------------|-----|------------------|-----|
| C &R Plan | N/A | Records & Reporting | N/A | Final Report | N/A |
| Geotechnical Inspection | N/A | Posting, Signage | N/A | Contingency Plan | N/A |
| Restorations Activities | N/A | Spills | N/A | O&M Plan | N/A |
| Maintenance | U | Modifications | N/A | Annual Report | N/A |

General Condition Comments:

ADDITIONAL COMMENTS/REMARKS

Inspected pit 312, no activity, Gate is open though

NON-COMPLIANCE/VIOLATIONS OF ACT OR LICENCE


No snow removal maintenance from silt fences causing silt fences to rip and pushed over
 With silt fences ripped and pushed over, allowing silt to enter fish bearing creeks causing changes in habitat to fish

Inspector's Signature: _____



«INSP_TYPE» WATER USE INSPECTION REPORT

INSPECTION IMAGES

| | |
|--|---|
| <p>Figure 1</p>  | <p>Figure 2</p>  |
| <p>Figure 3</p>  | <p>Figure 4</p>  |
| <p>Figure 5</p>  | <p>Figure 6</p>  |



«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 7



Figure 8



Figure 9



Figure 10



Figure 11



Figure 12





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 13



Figure 14



Figure 15



Figure 16



Figure 17



Figure 18





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 19

Figure 20



Figure 21

Figure 22



Figure 23

Figure 24





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 25



Figure 26



Figure 27



Figure 28



Figure 29



Figure 30





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 31



Figure 32



Figure 33



Figure 34



Figure 35



Figure 36





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 37



Figure 38



Figure 39



Figure 40



Figure 41



Figure 42





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 43



Figure 44



Figure 45




Figure 46



Figure 47



Figure 48





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 49



Figure 50



Figure 51



Figure 52

