



Beaufort Delta Region
P.O. Box 2100
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090



June 16, 2014

Northwest Territories Water Board
P.O. Box 2531
Inuvik, NT X0E 0T0

Attn: Freda Wilson, Office and Finance Administrator

**RE: INDUSTRIAL Water Use N7L1-1835
CLASS A – INDUSTRIAL
Inuvik – Tuktoyaktuk Highway – South End**

To: Ms. Wilson,

Please find the enclosed Inspection Report for your review and records.

An electronic copy (un-editable Adobe pdf.) has also been provided by e-mail.

If you have any questions or concerns regarding the enclosed, and/or if additional information is required please contact me at (867) 777-8909.

Regards,

ORIGINAL SIGNED

Donald Arey
Manager Resource Management
Department of Lands
Beaufort Delta Region-Inuvik

Cc:
Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



Beaufort Delta Region
Bag Service #1
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090

June 16, 2014

Government of the Northwest Territories - Department of Transportation
Lahm Ridge Tower, 2nd Floor, 4501 - 51 Avenue
P.O. Box 1320
Yellowknife, NT X1A 2L9

Attn: Larry Purcka

**RE: INDUSTRIAL Water Use N7L1-1835
CLASS A - INDUSTRIAL**

To: Larry Purcka,

An inspection of the above noted operation was conducted on June 13, 2014 by Manager Resource Management Donald Arey.

Enclosed is a copy of the Industrial Water Use Inspection Report.

If you have any questions, please contact me at 867 777-8900.

Regards,

ORIGINAL SIGNED

Donald Arey
Manager Resource Management
Department of Lands
Beaufort Delta Region

Cc:

Conrad Baetz, Regional Superintendent, Dept. of Lands, Beaufort Delta Region

Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources

LICENCEE:	Government of the Northwest Territories - Department of Transportation	PREVIOUS INSPECTION:	May 20, 2014
COMPANY REP:	Larry Purcka	INSPECTION DATE:	June 13, 2014

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

C &R Plan	N/A	Records & Reporting	A	Final Report	N/A
Geotechnical Inspection	A	Posting, Signage	N/A	Contingency Plan	N/A
Restorations Activities	A	Spills	N/A	O&M Plan	N/A
Maintenance	A	Modifications	N/A	Annual Report	N/A

General Condition Comments:

It should be noted that on the south east portion of the second bridge there is some erosion occurring as result of the spring freshette, inspector recommends that more armouring be placed in that area to avoid any further erosion to occur in that area. Aside from the above paragraph all aspects in relation to the water license were satisfactory.

ADDITIONAL COMMENTS/REMARKS

Inspector's Signature: _____

Aerial of road from start



Figure 2
source 1401A





Figure 4

