



June 6, 2016

Sent via email

Mr. Philippe Thibert-Leduc
Water Resource Officer
Environment and Natural Resources
Government of the Northwest Territories
PO Box 2749
Inuvik, NT X0E 0T0

Dear Mr. Thibert-Leduc:

Response to Inspection Report of 05/17/2016

This letter is to formally respond to the Inspection Report for water permit N7L1-1835 related to the Inuvik to Tuktoyaktuk Highway. Responses to the action items identified in your report follow. We have applied numbering to each request according to our new tracking system for regulator requests.

Hans Creek

2021 The Inspection Report of 05/17/2016 noted that silt fences at this site were failing. As of 05/20/2016 adjustments have been made to these silt fences and they are performing as required.

Trail Creek

2022 The Inspection Report of 05/17/2016 made the request to move or cover and contain earth piles. It is anticipated that these materials will be contained and covered by 06/10/2016.

2023 The Inspection Report of 05/17/2016 noted that there were no erosion and sediment control BMPs installed. It is anticipated that these measures will be installed by 06/10/2016.

Crossing 18

2024 The Inspection Report of 05/17/2016 noted that there were no erosion and sediment control BMPs installed. It is anticipated that these measures will be installed by 06/10/2016.

If you have questions regarding this information, please contact me at (867) 777-2716 or by email at dean_ahmet@gov.nt.ca.

Sincerely,

A handwritten signature in blue ink, appearing to read 'Ahmet', written in a cursive style.

Dean Ahmet, RET, PL(Eng.), BSc(Eng.), MPM, PMP
Senior Project Manager, ITH
Department of Transportation

cc: Mardy Semmler, Executive Director, Inuvialuit Water Board
Russell Newmark, CEO, EGT Northwind Ltd.