



Hamlet of Aklavik
Box 88, Aklavik, NT X0E 0A0

Ph: 867-978-2351
Fax: 867-978-2434

Dr. Bijaya Adhikari
Science and Regulatory Coordinator
Inuvialuit Water Board
Suite 302 – 125 Mackenzie Road
PO Box 2531
Inuvik, NT
X0E 0T0



March 19, 2015

Dear Dr. Adhikari

Thank you for your letter dated March 18, 2015, I hope the following will provide the requested information.

1. Sampling was not conducted on SNP 570-3 either during the spring or in the fall of 2014 and basically the reasoning is twofold. Firstly as the new SAO I was not aware as to the needs of the water license at the time. Secondly we did not have any sampling bottles to perform this task. We have now taken steps to ensure sampling will take place this spring and fall. Sampling bottles and shipping container have been requested from Taiga to be delivered soon.
 2. There was no spill training or operator training for the year of 2014.
 3. There is no inspection of dams, berms, dykes and control structures during the year.
 4. Through our staff monitoring of the solid waste site. Staff on a weekly basis push household garbage piles to flatten and compact. We also placed signage in areas of the solid waste site to identify where the various types of waste is to be stored. Also during the summer and fall months we were able to relocate miscellaneous garbage into segregated areas which has allowed more free room in the facility. This summer we will also be placing granular material over top of some of the household garbage site to further reduce space and reduce windblown material from escaping the site.
 5. To my knowledge we did not have an inspection or have any correspondence with the inspector regarding our infrastructure and facilities.
- If you have any further information required please feel free to contact me.

Yours Truly

Fred Behrens
Senior Admin Officer