



INDUSTRIAL WATER USE INSPECTION REPORT

DATE: AUGUST 19, 2002 COMPANY REP.: DAVE MITCHELL - LUMA / DCC REP.
 LICENSEE: REFENCE CONSTRUCTION CANADA LTD. (DCC) LICENCE #: N74-1784 / CAPE BERRY DEW LINE SITE.

WATER SUPPLY

Source: WATER SUPPLY LAKE Quantity Used: REFER TO RECORDS. Meter Rdg.: BY TRUCKLOAD.

Indicate:	A - Acceptable	U - Unacceptable	N/A - Not Applicable
Intake Facilities	<u>A</u>	Storage Structures	<u>N/A</u>
Flow Meas. Device	<u>A</u>	Conveyance Lines	<u>N/A</u>
		Treatment Systems	<u>N/A</u>
		Pumping Stations	<u>A</u>
		Recycling Modifications	<u>N/A</u>

Comments: LICENSEE HAD AN ADVERSE WATER QUALITY TEST THAT HAS THEM CONTEMPLATING AN ALTERNATIVE POTABLE WATER SOURCE.
NO OTHER PROBLEMS NOTED WITH WATER SUPPLY.

WASTE DISPOSAL

Tailings: N/A → Tailings Pond Natural Lake Underground
 Sewage: Sewage Treat. System Tailings Pond Natural Water Body
 Continuous Discharge Inter. Dischg.
 Solid Waste: Open Dump Landfill Burn & Bury Underground

Indicate:	A - Acceptable	U - Unacceptable	N/A - Not Applicable
Discharge Quality	<u>N/A</u>	Conveyance Lines	<u>N/A</u>
Decant Structures	<u>N/A</u>	Pond Treatment	<u>N/A</u>
Dyke Inspections	<u>A</u>	Runoff Diversion	<u>A</u>
		Disch. Meas. Dev.	<u>N/A</u>
		Dams, Dykes	<u>N/A</u>
		Erosion	<u>N/A</u>
		Freeboard	<u>A</u>
		Seepages	<u>N/A</u>
		Spills	<u>NONE REPORTED.</u>

Effluent Discharge Rate: N/A Samples Collected: BY LICENSEE AT SNP 1784-1.

Comments: SEWAGE/GREYWATER IS STORED IN A TWO CELL SUMP SYSTEM. THE LICENSEE IS RUNNING NO DISCHARGES OF SEWAGE EFFLUENT. LICENSEE PLANS TO MIX BURN COVER CAMP SUMP. INCUBATOR IN USE FOR DOMESTIC COMBUSTIBLES. SITE APPEARED NEAT AND TIDY.

GENERAL CONDITIONS

Indicate:	A - Acceptable	U - Unacceptable	N/A - Not Applicable
Ore & Waste Rock Stockpiles	<u>N/A</u>	Records & Reporting	<u>A</u>
Geotechnical Inspection	<u>BY LICENSEE.</u>	Posting, Signage	<u>A</u>
Restoration Activities	<u>ONGOING.</u>	New Construction	<u>A</u>
Mine Water Discharge	<u>N/A</u>	Chemical Storage	<u>N/A</u>
		Surv. Net. Prog.	<u>A</u>
		Contingency Plan	<u>A</u>
		Fuel Storage	<u>A</u>
		2002 Annual Report	<u>DUE MARCH 31, 2003.</u>

Comments: THE LICENSEE STATED NO REVISIONS TO THEIR ENVIRONMENTAL MONITORING PLAN.

Violations of Act or Licence: VIOLATION(S): 1. SNP PART B, ITEM 5; NO QA/QC PLAN SUBMITTED. THE LICENSEE WAS ASKED TO SUBMIT THE REQUIRED QA/QC PLAN, ASAP.

General Comments: LICENSEE WAS AWAITING A TRANSPORT CANADA INSPECTOR TO OVERSEE NEW PACKAGING AND SHIPPING REQUIREMENTS OF ROB LADEN MATERIAL. LICENSEE HOPES TO COMPLETE CLEAN UP THIS YEAR, ON OR ABOUT SEPTEMBER 25, 2002.

Page 2 attached Yes No

LUMA ENVIRONMENTAL SCIENTIST - DCC REP.
 Licensee Representative's Title

SCOTT GALLUPE - WATER RESOURCES OFFICER
 Inspector's Name

NOT AVAILABLE.
 Licensee Representative's Signature

Inspector's Signature