



May 28, 2015

Terence Hughes  
Regulatory and Community Affairs Advisor  
MGM Energy Corporation  
#4700, 888 – 3rd Street SW  
Calgary, AB T2P 5C5

Dear Mr. Hughes:

**Re: N7L1-1797 - MGM Energy Corporation, Burnt Lake Drilling – 2014 Annual Sump Environmental Inspection Report**

The Inuvialuit Water Board (IWB) accepts the above mentioned annual report submitted by MGM Energy Corporation along with the cover dated February 23, 2015 and supporting information provided April 29, 2015. The IWB reminds MGM it is a responsibility of the Licensee to maintain thermistors in working condition and comply with *Part H: Conditions Applying to Abandonment and Restoration*.

The submitted report including the IWB response will be placed on the IWB Public Register. Should you have any questions, please do not hesitate to contact me at 867-678-8610 or email: [adhikarib@nwtwb.com](mailto:adhikarib@nwtwb.com) or Mardy Semmler, Executive Director, at 867-678-8609 or email: [semmlerm@nwtwb.com](mailto:semmlerm@nwtwb.com).

Sincerely,

A handwritten signature in blue ink, appearing to read 'Bijaya Adhikari', with a horizontal line underneath.

Dr. Bijaya Adhikari  
Science and Regulatory Coordinator

cc: Philippe Thibert-Leduc, Water Resources Officer, ENR Inuvik