



Telephone: 867-678-6676
Fax: 867-678-6699

January 16, 2018

Government of the Northwest Territories - Department of Transportation
PO Box 2038
Inuvik, NT X0E 0T0

Attention: Dean Ahmet

File Number N7L1-1835
Type of Operation CLASS A - INDUSTRIAL
Location

Dear Dean Ahmet,

An inspection of the above noted operation was conducted on November 22, 2017 by Water Resources Officer Lloyd Gruben and EPO Alicia McRae .

Enclosed is a copy of the INDUSTRIAL Water Use Inspection Report.

If you have any questions, please contact me at 867-678-6676.

Sincerely,

Lloyd Gruben
Water Resources Officer
Environment and Natural Resources
Beaufort Delta

Cc:

Norm Snowshoe – Supt. Dept of ENR, Inuvik Region

Mardy Semmler – Executive Director, Inuvialuit Water Board

Bijaya Adhikara – Science and Regultor Coordinator, Inuvialuit Water Board



«INSP_TYPE» WATER USE INSPECTION REPORT

Freda Wilson – Inuvialuit Water Board

Date:	November 22, 2017	Licence #:	N7L1-1835	Page No:	2
-------	-------------------	------------	-----------	----------	---



«INSP_TYPE» WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1835	EXPIRY DATE:	December 11, 2023
LICENCEE:	Government of the Northwest Territories - Department of Transportation	PREVIOUS INSPECTION:	March 29, 2017
COMPANY REP:	Dean Ahmet	INSPECTION DATE:	November 22, 2017

WATER SUPPLY

Source:		Quantity Used:	
Owner/Operator:		Meter Reading:	

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Intake Facilities		Storage Structures		Treatment Systems		Recycling	
Flow Meas. Device		Conveyance Lines		Pumping Stations		Chem. Storage	
						Modifications	

Water Supply Comments:

WASTE DISPOSAL - SEWAGE

Disposal Method							
Mechanical	N	Camp Sump	N	Natural Water Body	N	Wetland Treatment	N
Continuous Discharge	N	Intermittent Discharge	N	Seasonal Discharge	N	Land Spread	N
Accelerated Biological	N	Other					

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Discharge Quality		Decant Process & Structures		Discharge Measurement Device	
Freeboard		Sludge Disposal Method			
Periods Of				SNP Samples Collected	



«INSP_TYPE» WATER USE INSPECTION REPORT

Discharge			
Effluent Discharge Rates			

Sewage Comments:

WASTE DISPOSAL - SOLID WASTE

Disposal Method							
Open Dump	N	Landfill	N	Burn & Landfill	N	Underground	N
Offsite Removal	N	Other					
Owner / Operator							

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Runoff Diversion		SNP Samples Collected	
------------------	--	-----------------------	--

Solid Waste Comments:

FUEL STORAGE

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Owner:	Dept of Infrastructure	Operator:	Dept of Infrastructure	Condition of tanks:	A
Berms & Liners	N/A	Water within Berm:	None	Evidence of Leaks:	Fuel

Drainage Pipes	N/A	Pump Station and Catchment Berm	N/A	Runoff Diversion	N/A
Pipeline Condition	N/A				

Fuel Storage Comments:



«INSP_TYPE» WATER USE INSPECTION REPORT

While doing the inspection at source 312, we stopped at the camp area. Did a walk around inspection. Went to the possible refueling station, we could smell strong odour of fuel. Grabbed a handful, sniffed, could smell fuel from the handful I grabbed

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

C &R Plan		Records & Reporting		Final Report	
Geotechnical Inspection		Posting, Signage		Contingency Plan	
Restorations Activities		Spills	U	O&M Plan	
Maintenance		Modifications		Annual Report	

General Condition Comments:

While inspecting the sediment control silt fences at Trail Valley Creek and Hans Creek, all silt fences are being pushed over from weight of snow. Ripping of silt fences also noted.

ADDITIONAL COMMENTS/REMARKS

NON-COMPLIANCE/VIOLATIONS OF ACT OR LICENCE

Inspector’s Signature: _____



«INSP_TYPE» WATER USE INSPECTION REPORT

INSPECTION IMAGES