

Bijaya Adhikari

From: Horton, Tyler D <tyler.d.horton@esso.ca>
Sent: November 26, 2018 11:24 AM
To: Bijaya Adhikari; Mardy Semmler
Cc: Morrish, Jenna (Calgary); Abel, Keri J
Subject: Bar-C 2018 Annual Water License Report
Attachments: 407011-00427-401-CA-LET-0001-BAR_C2018AnnualWaterLicenceN7L1-1836-Rev0.pdf

Hi Mardy & Bijaya,

As per the requirements listed in Part B.2 for Water License N7L1-1836, please see the attached 2018 Annual Report for the remediation work completed at Bar-C (Tununuk Point).

Please let me know if you have any questions or concerns regarding the attached document.

Thank you,

Tyler Horton, E.I.T.

Project Manager - Upstream

Environmental & Property Solutions, Imperial

505 Quarry Park Blvd S.E., Calgary, AB T2C 5N1 | C4A

tyler.d.horton@esso.ca | P 587.476.1416 | C 403.808.1784

imperialoil.ca | [Twitter](#) | [YouTube](#)



Advisian

WorleyParsons Group

Advisian
Suite 500, 151 Canada Olympic Rd SW
Calgary, AB T3B 6B7 CANADA
Phone: +1 403 247 0200
Toll-Free: 1 800 668 6772
Facsimile: +1 403 247 4811

A business of WorleyParsons Canada
Services Ltd.
www.advisian.com

23 November 2018

Proj. No.: 407011-00427-401

Inuvialuit Water Board
P.O. Box 2531
302, 125 Mackenzie Road
Inuvik, NT
X0E 0T0

Attention: Mardy Semmler, Executive Director

Dear Mr. Semmler:

**RE: BAR-C: Tununuk Point - 2018 Annual Report for Water Licence
N7L1-1836**

As per the requirements listed in Part B.2 for Water Licence Number N7L1-1836, Imperial Oil Resources Ventures Limited (Imperial) is pleased to provide the Inuvialuit Water Board (IWB) with the 2018 Annual Report for the remediation work completed at BAR-C (Tununuk Point; the Site).

Further details on site work completed in 2018 are provided below.

This information was prepared by WorleyParsons Canada Services Ltd., operating as Advisian, on behalf of Imperial.

a) Water Usage from Water Source

No water usage was required at the Site during 2018.

b) Sewage Accepted by the Town of Inuvik

No sewage was generated at or removed from Site during 2018.

c) Non-Hazardous Waste

No non-hazardous waste was generated at or removed from the Site during 2018. Buoys and signage were deployed in September 2018 to indicate three submerged sheet pile clusters remaining from the dock abandonment activities in 2017. These remaining sheet pile clusters are intended to be removed in 2019 in order to eliminate the navigational hazard.

d) Hazardous Waste

No hazardous waste was generated at or removed from the Site during 2018.



e) Waste Water Discharge

No waste water was generated at or discharged at the Site during 2018.

f) Bioremediation Facility Treated Soils

The bioremediation facility was decommissioned during the 2015 construction season. There were no soils with Type B petroleum hydrocarbons treated at the Site in 2018.

g) Surveillance Network Program Summary

The surveillance network monitoring stations (i.e., overland discharge points related to the remediation works) were decommissioned at the end of the 2015 construction season, as no further borrow material excavation or bioremediation was planned.

h) Monitoring Plan Summary

Capping of Landfills A and B was completed during the 2015 construction season. No additional thermistors or groundwater monitoring wells were installed in 2018.

A summary of the tasks associated with the ongoing Monitoring Plan for the landfills and waste disposal areas (WDAs) is presented below:

a) Groundwater Monitoring

Baseline groundwater monitoring was completed in 2015 (Year 1) and groundwater monitoring (Year 3) was completed in 2017. At present, there are insufficient data to determine any statistical trends per the Abandoned Military Site Remediation Protocol (AMSRP). The next scheduled groundwater monitoring event is in 2019.

b) Post-Construction Monitoring

Baseline post-construction monitoring and inspection of the landfills and WDAs was completed in 2015 (Year 1) and 2017 (Year 3). Download of thermistor data, replacement of thermistor batteries and landfill cap integrity assessments are next scheduled for 2019 (Year 5).

c) Natural Environment Monitoring

Natural environment data were not collected during 2018 due to limited Site presence.

i) Reclamation Activity Summary

No additional reclamation activities were completed in 2018.

j) Modifications to the Reclamation Project

No modifications were made to the reclamation project in 2018.



k) Studies

No studies were required by the IWB in 2018 and no future studies are planned.

l) Plan Updates

- a) Waste Management Plan
No updates or revisions were made to this plan in 2018.
- b) Spill Contingency Plan
No updates or revisions were made to this plan in 2018.
- c) Quality Assurance/Quality Control Plan
No updates or revisions were made to this plan in 2018.
- d) Monitoring Plan
No updates or revisions were made to this plan in 2018.
- e) Remedial Action Plan
No updates or revisions were made to this plan in 2018.

m) Discharges and Spills

No discharges or spills occurred in 2018.

n) Spill Training

Training on spill mitigation and clean up procedures was included as part of the pre-mobilization discussions with on site staff and subcontractors, during the project kick-off meetings or during Site orientation.

Closure

We trust that the information provided satisfies the conditions of the Water Licence Part B.2. Please feel free to contact the undersigned if you have any questions or comments.

Sincerely,

A handwritten signature in black ink, appearing to read 'Jenna Morrish'.

Jenna Morrish, M.Sc.(Eng.), P.Eng.
Staff Environmental Engineer

Advisian, Americas