



Beaufort Delta Region
Bag Service #1
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090

August 5, 2014

Inuvialuit Water Board
P.O. Box 2531
Inuvik, NT X0E 0T0

Attn: Freda Wilson, Office and Finance Administrator

**RE: INDUSTRIAL Water Use N7L1-1836
CLASS B – INDUSTRIAL
BAR-C**

To: Ms. Wilson,

Please find the enclosed Inspection Report for your review and records.

An electronic copy (un-editable Adobe pdf.) has also been provided by e-mail.

If you have any questions or concerns regarding the enclosed, and/or if additional information is required please contact me at (867) 777-8900.

Regards,

Donald Arey
Manager Resource Management
Department of Lands
Beaufort Delta Region-Inuvik

Cc:

Conrad Baetz, Superintendent, Dept. of Lands, Beaufort Delta Region
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



Beaufort Delta Region
Bag Service #1
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090

August 5, 2014

Imperial Oil Resources
237-4th Ave. SW
P.O Box 2480 Station M
Calgary, AB T2P 3M9

Attn: Mr. John Bertrand

**RE: INDUSTRIAL Water Use N7L1-1836
CLASS B - INDUSTRIAL**

Dear Mr. John Bertrand,

An inspection of the above noted operation was conducted on July 31, 2014 by Manager Resource Management Donald Arey.

Enclosed is a copy of the Industrial Water Use Inspection Report.

If you have any questions, please contact me at 867 777-8900.

Sincerely,

A handwritten signature in black ink, appearing to read "Donald Arey", written over a faint, larger version of the same signature.

Donald Arey
Manager Resource Management
Department of Lands
Beaufort Delta Region

Cc: IWB

Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1836	EXPIRY DATE:	March 30, 2020
LICENCEE:	Imperial Oil Resources	PREVIOUS INSPECTION:	New
COMPANY REP:	Mr. John Bertrand	INSPECTION DATE:	July 31, 2014

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

C &R Plan	N/I	Records & Reporting	N/I	Final Report	N/A
Geotechnical Inspection	N/A	Posting, Signage	A	Contingency Plan	A
Restorations Activities	A	Spills	N/A	O&M Plan	N/I
Maintenance	A	Modifications	A	Annual Report	N/A

General Condition Comments:

During this inspection all areas as per plans were being implemented, no non-compliance issues were observed. It would be appreciated to have a list of contacts with regards to the program in the event that an inspector may need to contact them at site.

Inspector's Signature:



WATER USE INSPECTION REPORT

Inspection Images:

Figure 1

Area E for Hydro Carbon soil



Figure 2

Camp Barge



WATER USE INSPECTION REPORT

Figure 3
Aerial North view



Figure 4
Concrete area

