



March 1, 2019

Mr. Joshua Clark
Environmental Analyst
Northwest Territories Power Corporation
4 Capital Drive
Hay River, NT X0E 1G2

Dear Mr. Clark:

Re: N3L8-1838 – Northwest Territories Power Corporation, Remediation and Reclamation - Aklavik former Power Plant Site – 2018 Annual Report

The Inuvialuit Water Board (IWB) acknowledges receipt of the 2018 annual report. Upon review, information gaps were noted as required by Water Licence N3L8-1838 Part B: General Conditions, Item 1.

Please provide the following information:

1. Part B, Item 1b): the monthly and annual quantities in cubic metres (m³) of treated contaminated soil at the bio-treatment facility;
2. Part B, Item 1c): all laboratory results and analysis of all data collected during each SNP sampling period;
3. Part B, Item 1d): a list and description including location and volumes of all unauthorized discharges and spills, and summaries of all associated remediation activities and follow-up action taken;
4. Part B, Item 1e): a description of any spill and operational training carried out;
5. Part B, Item 1g): a summary of remediation, reclamation and closure activities completed; and
6. Part B, Item 1h): a description of any work anticipated for the next year (i.e. 2019).

Please submit two (2) hard copies and two (2) electronic copies (CD's or USB's) of the above additional information requested. Submitted documentation, including all related IWB correspondence, will be placed on the IWB Public Register.

Should you have any questions or concerns regarding this correspondence contact me at 867-678-8610 or adhikarib@inuvwb.ca.

Sincerely,

Bijaya Adhikari, PhD
Science and Regulatory Coordinator

cc: Lloyd Gruben, Water Resources Officer - ENR Inuvik