



Telephone: 867-777-8907
Fax: 867-777-2090

October 29, 2020

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Merl Carpenter

File Number N7L1-1835
Type of Operation CLASS A - INDUSTRIAL
Location

Dear Mr. Carpenter,

An inspection of the above noted operation was conducted on October 28, 2020 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the INDUSTRIAL Water Use Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

Cc:

Norman Snowshoe, Superintendent, Environment and Natural Resources, Beaufort Delta

Richard Binder, Inuvialuit Water Board

Bag Service 1, Inuvik, NT X0E 0T0



«INSP_TYPE» WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1835	EXPIRY DATE:	December 11, 2023
LICENCEE:	Government of the Northwest Territories - Department of Transportation	PREVIOUS INSPECTION:	May 31, 2019
COMPANY REP:	Merl Carpenter	INSPECTION DATE:	October 28, 2020

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

C &R Plan	N/A	Records & Reporting		Final Report	N/A
Geotechnical Inspection	N/A	Posting, Signage	A	Contingency Plan	
Restorations Activities	A	Spills	A	O&M Plan	
Maintenance	A	Modifications	N/A	Annual Report	N/A

General Condition Comments:

During the inspections on October 28, 2020 along the Inuvik - Tuktoyaktuk Highway we inspected all the bridges and some culverts and there were no concerns observed by the inspectors.

All the bridges and culverts were free of any obstructions and are flowing freely where not frozen, there is no water pooling along the highway due blockages.

All the silt fences that were noticeable along the highway were in good condition.

Please ensure that any reports which are required for this water licence are submitted to the board in a timely manner.

ADDITIONAL COMMENTS/REMARKS

NON-COMPLIANCE/VIOLATIONS OF ACT OR LICENCE

Inspector's Signature:





«INSP_TYPE» WATER USE INSPECTION REPORT

INSPECTION IMAGES

Figure 1



Figure 2





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 3



Figure 4





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 5



Figure 6





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 7



Figure 8





«INSP_TYPE» WATER USE INSPECTION REPORT

Figure 9



Figure 10

