



Beaufort Delta Region
P.O. Box 2100
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090

December 4, 2014

Inuvialuit Water Board
P.O. Box 2531
Inuvik, NT X0E 0T0

Attn: Freda Wilson, Office and Finance Administrator

**RE: INDUSTRIAL Water Use N7L1-1835
CLASS A – INDUSTRIAL
Inuvik – Tuktoyaktuk Highway – South End**

To: Ms. Wilson,

Please find the enclosed Inspection Report for your review and records.

An electronic copy (un-editable Adobe pdf.) has also been provided by e-mail.

If you have any questions or concerns regarding the enclosed, and/or if additional information is required please contact me at (867) 777-8909.

Regards,

ORIGINAL SIGNED

Donald Arey
Manager Resource Management
Department of Lands
Beaufort Delta Region-Inuvik

Cc:
Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



Beaufort Delta Region
Bag Service #1
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090

December 4, 2014

Government of the Northwest Territories - Department of Transportation
Lahm Ridge Tower, 2nd Floor, 4501 - 51 Avenue
P.O. Box 1320
Yellowknife, NT X1A 2L9

Attn: Larry Purcka

**RE: INDUSTRIAL Water Use N7L1-1835
CLASS A – INDUSTRIAL South End**

To: Larry Purcka,

An inspection of the above noted operation was conducted on December 03, 2014 by the under signed and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Industrial Water Use Inspection Report.

If you have any questions, please contact me at 867 777-8900.

Regards,

ORIGINAL SIGNED

Donald Arey
Manager Resource Management
Department of Lands
Beaufort Delta Region

Cc: Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region,
Stephen Charlie, Superintendent, Depart. of Environment and Natural Resources



«INSP_TYPE» WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1835	EXPIRY DATE:	December 11, 2023
LICENCEE:	Government of the Northwest Territories - Department of Transportation	PREVIOUS INSPECTION:	December 01, 2014
COMPANY REP:	Larry Purcka	INSPECTION DATE:	December 03, 2014

WASTE DISPOSAL – MINING – OTHER

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Ore & Waste Rock Stockpiles	A	Chemical Storage	N/A
Ground Water Discharge	N/A	Mine Water Discharge	N/A

Mining-Other Comments:

Stock piles of the over-burden are currently being done on the north and south west sides of the Source 1401A, no environmental concerns observed.

FUEL STORAGE

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Owner:	EGT/NWI	Operator:	NWI	Condition of tanks:	A
Berms & Liners	N/A	Water within Berm:	N/A	Evidence of Leaks:	Nil
Drainage Pipes	N/A	Pump Station and Catchment Berm	A	Runoff Diversion	N/A
Pipeline Condition	N/A				

Fuel Storage Comments:

Fuel storage area was all satisfactory during this inspection.

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

C &R Plan	N/A	Records & Reporting	N/A	Final Report	N/A
Geotechnical Inspection	N/A	Posting, Signage	N/I	Contingency Plan	N/A
Restorations Activities	A	Spills	N/A	O&M Plan	N/A
Maintenance	N/A	Modifications	N/A	Annual Report	N/A

General Condition Comments:

Access to source 1401A is satisfactory with continued work. Source 1401A hauling of material is in progress, over-burden stock piles are being resloped at the north and south west corners of the pit to ensure proper drainage. No environmental concerns were observed during this inspection.

Inspector's Signature: _____

«INSP_TYPE» WATER USE INSPECTION REPORT

Inspection Images:

Figure 1

Aerial of source 1401A



Figure 2

road construction past the first bridge



Figure 3

access road of source 1401A



Figure 4

detour by bridge

