



Beaufort Delta Region
Bag Service #1
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090

December 17, 2014

Government of the Northwest Territories - Department of Transportation
Lahm Ridge Tower, 2nd Floor, 4501 - 51 Avenue
P.O. Box 1320
Yellowknife, NT X1A 2L9

Attn: Larry Purcka

**RE: INDUSTRIAL Water Use N7L1-1835
CLASS A – INDUSTRIAL – South end**

To: Larry Purcka,

An inspection of the above noted operation was conducted on December 16, 2014 by the under signed and Regional Superintendent Conrad Baetz.

Enclosed is a copy of the Industrial Water Use Inspection Report.

If you have any questions, please contact me at 867 777-8900.

Regards,

ORIGINAL SIGNED

Donald Arey
Manager Resource Management
Department of Lands
Beaufort Delta Region

Cc: Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region,
Stephen Charlie, Superintendent, Depart. of Environment and Natural Resources



«INSP_TYPE» WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1835	EXPIRY DATE:	December 11, 2023
LICENCEE:	Government of the Northwest Territories - Department of Transportation	PREVIOUS INSPECTION:	December 03, 2014
COMPANY REP:	Larry Purcka	INSPECTION DATE:	December 16, 2014

WASTE DISPOSAL – MINING – OTHER

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Ore & Waste Rock Stockpiles	N/A	Chemical Storage	N/A
Ground Water Discharge	N/A	Mine Water Discharge	N/A

Mining-Other Comments:

At source 1401A the over-burden material are stock piled in a rectangular shape at the northwest and southwest corner locations of the pit. Sloping of the pit looks good and material is being excavated and removed for the road construction. All aspects are satisfactory.

FUEL STORAGE

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Owner:	EGT/NWI	Operator:	NWI	Condition of tanks:	A
Berms & Liners	N/A	Water within Berm:	NIL	Evidence of Leaks:	NIL
Drainage Pipes	N/A	Pump Station and Catchment Berm	A	Runoff Diversion	N/A
Pipeline Condition	N/A				

Fuel Storage Comments:

All aspects were satisfactory at the time of the inspection.

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

C &R Plan	N/I	Records & Reporting	N/I	Final Report	N/A
Geotechnical Inspection	N/A	Posting, Signage	N/I	Contingency Plan	N/I
Restorations Activities	N/I	Spills	A	O&M Plan	N/I
Maintenance	A	Modifications	N/A	Annual Report	N/A

General Condition Comments:

Over-all all aspects in regards to the WL. were satisfactory with no environmental concerns. Granular material is currently being laid on just past the south side first bridge.

ORIGINAL SIGNED

Inspector's Signature: _____

Date:	December 16, 2014	Licence #:	N7L1-1835	Page No:	1
-------	-------------------	------------	-----------	----------	---

«INSP_TYPE» WATER USE INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2



Figure 3



Figure 4

