



Beaufort Delta Region  
P.O. Box 2100  
Inuvik, NT X0E 0T0

Telephone: 867 777-8900  
Fax: 867-777-2090

January 7, 2015

Northwest Territories Water Board  
P.O. Box 2531  
Inuvik, NT X0E 0T0

**Attn: Freda Wilson, Office and Finance Administrator**

**RE: INDUSTRIAL Water Use N7L1-1835  
CLASS A – INDUSTRIAL  
Inuvik – Tuktoyaktuk Highway – South End**

To: Ms. Wilson,

Please find the enclosed Inspection Report for your review and records.

An electronic copy (un-editable Adobe pdf.) has also been provided by e-mail.

If you have any questions or concerns regarding the enclosed, and/or if additional information is required please contact me at (867) 777-8909.

Regards,

**ORIGINAL SIGNED**

Donald Arey  
Manager Resource Management  
Department of Lands  
Beaufort Delta Region-Inuvik

Cc:

Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region  
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



Beaufort Delta Region  
Bag Service #1  
Inuvik, NT X0E 0T0

Telephone: 867 777-8900  
Fax: 867-777-2090

January 7, 2015

Government of the Northwest Territories - Department of Transportation  
Lahm Ridge Tower, 2nd Floor, 4501 - 51 Avenue  
P.O. Box 1320  
Yellowknife, NT X1A 2L9

**Attn: Larry Purcka**

**RE: INDUSTRIAL Water Use N7L1-1835  
CLASS A – INDUSTRIAL  
Inuvik – Tuktoyaktuk Highway – South End**

To: Larry Purcka,

An inspection of the above noted operation was conducted on January 06, 2015 by the undersigned and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Industrial Water Use Inspection Report.

If you have any questions, please contact me at 867 777-8900.

Regards,

**ORIGINAL SIGNED**

Donald Arey  
Manager Resource Management  
Department of Lands  
Beaufort Delta Region

Cc: Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region,  
Stephen Charlie, Superintendent, Depart. of Environment and Natural Resources



## INDUSTRIAL WATER USE INSPECTION REPORT

|                     |  |                             |                   |
|---------------------|--|-----------------------------|-------------------|
| <b>LICENCE #:</b>   | N7L1-1835  | <b>EXPIRY DATE:</b>         | December 11, 2023 |
| <b>LICENCEE:</b>    | Government of the Northwest Territories - Department of Transportation | <b>PREVIOUS INSPECTION:</b> | December 16, 2014 |
| <b>COMPANY REP:</b> | Larry Purcka   | <b>INSPECTION DATE:</b>     | January 06, 2015  |

### WASTE DISPOSAL – MINING – OTHER

**Indicate:**      **A - Acceptable**                      **U - Unacceptable**                      **N/A - Not Applicable**      **N/I - Not Inspected**

|                             |     |                      |     |
|-----------------------------|-----|----------------------|-----|
| Ore & Waste Rock Stockpiles | N/A | Chemical Storage     | N/A |
| Ground Water Discharge      | N/A | Mine Water Discharge | N/A |

#### **Mining-Other Comments:**

All matters in relation to Source 1401A were acceptable with no environmental concerns. Hauling currently in progress.

### FUEL STORAGE

**Indicate:**      **A - Acceptable**                      **U - Unacceptable**                      **N/A - Not Applicable**      **N/I - Not Inspected**

|                    |     |                                 |     |                     |     |
|--------------------|-----|---------------------------------|-----|---------------------|-----|
| Owner:             | NWI | Operator:                       | NWI | Condition of tanks: | A   |
| Berms & Liners     | N/A | Water within Berm:              | NIL | Evidence of Leaks:  | NIL |
| Drainage Pipes     | N/A | Pump Station and Catchment Berm | A   | Runoff Diversion    | N/A |
| Pipeline Condition | N/A |                                 |     |                     |     |

#### **Fuel Storage Comments:**

All aspects were satisfactory at the time of inspection.

### GENERAL CONDITIONS/REPORTS/PLANS

**Indicate:**      **A - Acceptable**                      **U - Unacceptable**                      **N/A - Not Applicable**      **N/I - Not Inspected**

|                         |     |                     |     |                  |     |
|-------------------------|-----|---------------------|-----|------------------|-----|
| C &R Plan               | N/A | Records & Reporting | A   | Final Report     | N/A |
| Geotechnical Inspection | N/A | Posting, Signage    | N/I | Contingency Plan | A   |
| Restorations Activities | A   | Spills              | N/A | O&M Plan         | N/I |
| Maintenance             | A   | Modifications       | N/A | Annual Report    | N/A |

#### **General Condition Comments:**

Overall all aspects observed were satisfactory, however it was observed that the silt fencing in some areas was buried with granular material from the road.

Inspector's Signature: \_\_\_\_\_

## INDUSTRIAL WATER USE INSPECTION REPORT

Inspection Images:

**Figure 1**

**Sorce 1401A**



**Figure 2**

**1401A drilling**



**Figure 3**  
fuel storage



**Figure 4**  
silt fencing



**Figure 5**  
silt fencing



**Figure 6**  
silt fencing

