



Beaufort Delta Region  
P.O. Box 2100  
Inuvik, NT X0E 0T0

Telephone: 867 777-8900  
Fax: 867-777-2090

February 11, 2015

Inuvialuit Water Board  
P.O. Box 2531  
Inuvik, NT X0E 0T0

**Attn: Freda Wilson, Office and Finance Administrator**

**RE: INDUSTRIAL Water Use N7L1-1835  
CLASS A – INDUSTRIAL  
Inuvik – Tuktoyaktuk Highway**

To: Ms. Wilson,

Please find the enclosed Inspection Report for your review and records.

An electronic copy (un-editable Adobe pdf.) has also been provided by e-mail.

If you have any questions or concerns regarding the enclosed, and/or if additional information is required please contact me at (867) 777-8900.

Regards,

A handwritten signature in black ink, appearing to read "D. Arey".

Donald Arey  
Manager Resource Management  
Department of Lands  
Beaufort Delta Region-Inuvik

Cc:  
Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region  
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



LANDS

Beaufort Delta Region  
Bag Service #1  
Inuvik, NT X0E 0T0

Telephone: 867 777-8900  
Fax: 867-777-2090

February 11, 2015

Government of the Northwest Territories - Department of Transportation  
Lahm Ridge Tower, 2nd Floor, 4501 - 51 Avenue  
P.O. Box 1320  
Yellowknife, NT X1A 2L9

**Attn: Larry Purcka**

**RE: INDUSTRIAL Water Use N7L1-1835  
CLASS A - INDUSTRIAL**

To: Larry Purcka,

An inspection of the above noted operation was conducted on February 06, 2015 by the undersigned and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Industrial Water Use Inspection Report.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager Resource Management  
Department of Lands  
Beaufort Delta Region

Cc: Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region,  
Stephen Charlie, Superintendent, Depart. of Environment and Natural Resources



## INDUSTRIAL WATER USE INSPECTION REPORT

<b>LICENCE #:</b>	N7L1-1835	<b>EXPIRY DATE:</b>	December 11, 2023
<b>LICENCEE:</b>	Government of the Northwest Territories - Department of Transportation	<b>PREVIOUS INSPECTION:</b>	February 03, 2015
<b>COMPANY REP:</b>	Larry Purcka	<b>INSPECTION DATE:</b>	February 06, 2015

### WASTE DISPOSAL – MINING – OTHER

**Indicate:**      **A - Acceptable**              **U - Unacceptable**              **N/A - Not Applicable**      **N/I - Not Inspected**

Ore & Waste Rock Stockpiles	N/A	Chemical Storage	N/A
Ground Water Discharge	N/A	Mine Water Discharge	N/A

#### **Mining-Other Comments:**

Access currently under construction to Source PW 10-11, source 170 and 174 work currently in progress with no environmental concerns observed.

### FUEL STORAGE

**Indicate:**      **A - Acceptable**              **U - Unacceptable**              **N/A - Not Applicable**      **N/I - Not Inspected**

Owner:	EGT	Operator:	EGT	Condition of tanks:	A
Berms & Liners	A	Water within Berm:	NIL	Evidence of Leaks:	NIL
Drainage Pipes	N/A	Pump Station and Catchment Berm	A	Runoff Diversion	N/A
Pipeline Condition	N/A				

#### **Fuel Storage Comments:**

All aspects with regards to the Fuel storages were acceptable at the time of the inspection.

### GENERAL CONDITIONS/REPORTS/PLANS

**Indicate:**      **A - Acceptable**              **U - Unacceptable**              **N/A - Not Applicable**      **N/I - Not Inspected**

C &R Plan	N/I	Records & Reporting	A	Final Report	N/I
Geotechnical Inspection	N/I	Posting, Signage	N/I	Contingency Plan	N/I
Restorations Activities	N/A	Spills	A	O&M Plan	N/I
Maintenance	A	Modifications	N/A	Annual Report	N/I

#### **General Condition Comments:**

During the inspection it was observed at the maintenance shop area a rock truck idling with no drip tray. Aside from this no other environmental concerns were observed. For the accesses please ensure that the DFO's 2010 "Protocol for Water Withdrawal from ice covered Waterbodies in the Northwest Territories and Nunavut" are adhered to.

Inspector's Signature: \_\_\_\_\_

## INDUSTRIAL WATER USE INSPECTION REPORT

Inspection Images:

**Figure 1**

**PW 10 - 11 access**



**Figure 2**

**Source 170 acces**



## INDUSTRIAL WATER USE INSPECTION REPORT

**Figure 3**

**North end access to 174**



**Figure 4**

**South end access to 174**



**Figure 5**  
source 170



**Figure 6**  
At the Source 170 camp area a parked and idling rock truck with no drip tray.



## INDUSTRIAL WATER USE INSPECTION REPORT

**Figure 7**

Source 170 camp fuel storage area.



**Figure 8**

Source 174

