



Beaufort Delta Region
P.O. Box 2100
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090



March 13, 2015

Inuvialuit Water Board
P.O. Box 2531
Inuvik, NT X0E 0T0

Attn: Freda Wilson, Office and Finance Administrator

**RE: INDUSTRIAL Water Use N7L1-1835
CLASS A – INDUSTRIAL
Inuvik – Tuktoyaktuk Highway – North End**

To: Ms. Wilson,

Please find the enclosed Inspection Report for your review and records.

An electronic copy (un-editable Adobe pdf.) has also been provided by e-mail.

If you have any questions or concerns regarding the enclosed, and/or if additional information is required please contact me at (867) 777-8900.

Regards,

A handwritten signature in black ink, appearing to read "Herbert Allen".

Herbert Allen
Resource Management Officer II
Department of Land
Beaufort Delta Region
Bag service #1
Inuvik, NT
X0E0T0

Cc:

Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



Beaufort Delta
Bag Service !
Inuvik, NT X0E 0T0

Telephone: 867-777-8907
Fax: 867-777-2090

March 13, 2015

Government of the Northwest Territories - Department of Transportation
Lahm Ridge Tower, 2nd Floor, 4501 - 51 Avenue
P.O. Box 1320
Yellowknife, NT X1A 2L9

Attn: Larry Purcka

**RE: INDUSTRIAL Water Use N7L1-1835
CLASS A – INDUSTRIAL North end**

Dear Larry Purcka,

An inspection of the above noted operation was conducted on March 12, 2015 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Industrial Water Use Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

A handwritten signature in black ink, appearing to read "H. Allen", written over a light blue grid background.

Herbert Allen
Resource Management Officer II
Department of Land
Beaufort Delta Region
Bag service #1
Inuvik, NT
X0E0T0

Cc: Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



«INSP_TYPE» WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1835	EXPIRY DATE:	December 11, 2023
LICENCEE:	Government of the Northwest Territories - Department of Transportation	PREVIOUS INSPECTION:	March 12, 2015
COMPANY REP:	Larry Purcka	INSPECTION DATE:	March 12, 2015

WASTE DISPOSAL – SEWAGE

Disposal Method							
Mechanical	N	Camp Sump	N	Natural Water Body	N	Wetland Treatment	N
Continuous Discharge	N	Intermittent Discharge	N	Seasonal Discharge	N	Land Spread	N
Accelerated Biological	N	Other	Pump out to approved facility				

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Discharge Quality	N/A	Decent Process & Structures	N/A	Discharge Measurement Device	N/A
Freeboard	N/A	Sludge Disposal Method	N/A		
Periods Of Discharge	N/A			SNP Samples Collected	N/A
Effluent Discharge Rates	N/A				

Sewage Comments:

During the inspection at the 3 camps sewage disposal at the north end of the Inuvik Tuk highway construction area there were no environmental concerns observed by the inspector.

WASTE DISPOSAL – SOLID WASTE

Disposal Method		Incineration					
Open Dump	N	Landfill	N	Burn & Landfill	N	Underground	N
Offsite Removal	N	Other					
Owner / Operator	E-Grubens Transportation LTD						

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Runoff Diversion	N/I	SNP Samples Collected	
------------------	-----	-----------------------	--

Solid Waste Comments:

During the inspection at the 3 camps solid waste disposal at the north end of the Inuvik Tuk highway construction area there were no environmental concerns observed by the inspector.

FUEL STORAGE

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**



«INSP TYPE» WATER USE INSPECTION REPORT

Owner:	E-Grubens Transortation LTD	Operator:	E-Grubens Transortation LTD	Condition of tanks:	A
Berms & Liners	A	Water within Berm:	NIL	Evidence of Leaks:	NIL
Drainage Pipes	N/A	Pump Station and Catchment Berm	A	Runoff Diversion	N/A
Pipeline Condition	N/A				

Fuel Storage Comments:

During the inspection of the fuel storage at the north end of the Inuvik Tuk highway construction area there were no envirmmental concerns observed by the inspector.

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable N/I - Not Inspected

C &R Plan	N/I	Records & Reporting	A	Final Report	N/I
Geotechnical Inspection	N/I	Posting, Signage	N/I	Contingency Plan	N/I
Restorations Activities	N/I	Spills	A	O&M Plan	N/I
Maintenance	A	Modifications	N/I	Annual Report	N/I

General Condition Comments:

During the inspection of the 3 camp locations, stream crossings and colverts at the north end of the Inuvik Tuk highway construction area there were no envirmmental concerns observed by the inspector.

Inspector's Signature:



«INSP_TYPE» WATER USE INSPECTION REPORT

Inspection Images:

Figure 1

First bridge from the north to south




Figure 2

Second Bridge in construction from the north to south



Figure 3
Fuel Storage at camp 170



Figure 4
Colverts on the ice at camp 170

