



Beaufort Delta Region
P.O. Box 2100
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090



April 2, 2015

Inuvialuit Water Board
P.O. Box 2531
Inuvik, NT X0E 0T0

Attn: Freda Wilson, Office and Finance Administrator

**RE: INDUSTRIAL Water Use N7L1-1835
CLASS A – INDUSTRIAL
Inuvik – Tuktoyaktuk Highway – North End**

To: Ms. Wilson,

Please find the enclosed Inspection Report for your review and records.

An electronic copy (un-editable Adobe pdf.) has also been provided by e-mail.

If you have any questions or concerns regarding the enclosed, and/or if additional information is required please contact me at (867) 777-8900.

Regards,

A handwritten signature in blue ink, appearing to read "D. Arey".

Donald Arey
Manager Resource Management
Department of Lands
Beaufort Delta Region-Inuvik

Cc:
Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



Beaufort Delta Region
Bag Service #1
Inuvik, NT X0E 0T0

Telephone: 867 777-8900
Fax: 867-777-2090

April 2, 2015

Government of the Northwest Territories - Department of Transportation
Lahm Ridge Tower, 2nd Floor, 4501 - 51 Avenue
P.O. Box 1320
Yellowknife, NT X1A 2L9

Attn: Binay Yadav

**RE: INDUSTRIAL Water Use N7L1-1835
CLASS A – INDUSTRIAL -North End**

To: Binay Yadav,

An inspection of the above noted operation was conducted on March 20, 2015 by Manager Resource Management Donald Arey and Water Resource Officer Philippe Thibert-Leduc.

Enclosed is a copy of the Industrial Water Use Inspection Report.

If you have any questions, please contact me at 867 777-8900.

Regards,

A handwritten signature in blue ink, appearing to read "D. Arey".

Donald Arey
Manager Resource Management
Department of Lands
Beaufort Delta Region

**Cc: Conrad Baetz, Superintendent Dept. of Lands, Beaufort Delta Region,
Stephen Charlie, Superintendent, Depart. of Environment and Natural Resources**



INDUSTRIAL WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1835	EXPIRY DATE:	December 11, 2023
LICENCEE:	Government of the Northwest Territories - Department of Transportation	PREVIOUS INSPECTION:	March 12, 2015
COMPANY REP:	Larry Purecka	INSPECTION DATE:	March 20, 2015

WASTE DISPOSAL – SEWAGE

Disposal Method		Trucked out					
Mechanical	N	Camp Sump	N	Natural Water Body	N	Wetland Treatment	N
Continuous Discharge	N	Intermittent Discharge	N	Seasonal Discharge	N	Land Spread	N
Accelerated Biological	N	Other					

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Discharge Quality	N/I	Decent Process & Structures	N/I	Discharge Measurement Device	N/I
Freeboard	N/A	Sludge Disposal Method	N/A		
Periods Of Discharge	N/I			SNP Samples Collected	N/I
Effluent Discharge Rates	N/I				

Sewage Comments:

During the inspection nothing evident found in regards to waste disposal.

WASTE DISPOSAL – MINING – OTHER

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Ore & Waste Rock Stockpiles	N/A	Chemical Storage	N/A
Ground Water Discharge	A	Mine Water Discharge	N/A

Mining-Other Comments:

All aspect were satisfactory at time of inspection, although it was observed after further review at the Dept. Of Lands office from the GPS track taken that work is being conducted on Territorial Lands with-out the Proper Authorizations.

As you are well aware the terms and conditions of the Water License under Part B Item 13 and 17 States the following:

"13. The Licensee shall ensure that all Contractors and Sub-Contractors are aware of, and shall conform to, all Terms and Conditions of this Licence.

"17. Compliance with the terms and conditions of this Licence does not absolve the Licensee from responsibility for compliance with the requirements of all applicable Federal, Territorial and Municipal legislation for which any and all applicable licences and permits shall also be obtained by Licensee."

As no Land Use Permit or a Quarry Permit was issued for work on Territorial Lands the above has put you in non-compliance, it is recommended that actions be taken to correct the non-compliance immediately.

WASTE DISPOSAL – SOLID WASTE

Disposal Method		Trucked out					
Open Dump	N	Landfill	N	Burn & Landfill	N	Underground	N



INDUSTRIAL WATER USE INSPECTION REPORT

Offsite Removal	Y	Other	
Owner / Operator	EGT		

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Runoff Diversion	N/A	SNP Samples Collected	
------------------	-----	-----------------------	--

Solid Waste Comments:
All aspects with solid wastes were satisfactory at the time of the inspection.

FUEL STORAGE

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Owner:	EGT	Operator:	EGT	Condition of tanks:	A
Berms & Liners	A	Water within Berm:	Nil	Evidence of Leaks:	Nil
Drainage Pipes	N/A	Pump Station and Catchment Berm	A	Runoff Diversion	N/A
Pipeline Condition	N/A				

Fuel Storage Comments:
No environmental concerns were evident at the time of inspection.

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

C & R Plan	N/I	Records & Reporting	N/I	Final Report	N/I
Geotechnical Inspection	N/I	Posting, Signage	N/I	Contingency Plan	N/I
Restorations Activities	N/I	Spills	A	O&M Plan	N/I
Maintenance	A	Modifications	N/I	Annual Report	N/I

General Condition Comments:
As previously mentioned for the Mining aspect; All aspect were satisfactory at time of inspection, although it was observed after further review at the Dept. Of Lands office from the GPS track taken that work is being conducted on Territorial Lands with-out the Proper Authorzations.

As you are well aware the terms and conditions of the Water License under Part B Item 13 and 17 States the following:

"13. The Licensee shall ensure that all Contractors and Sub-Contractors are aware of, and shall conform to, all Terms and Conditions of this Licence.

"17. Compliance with the terms and conditions of this Licence does not absolve the Licensee from responsibility for compliance with the requirements of all applicable Federal, Territorial and Municipal legislation for which any and all applicable licences and permits shall also be obtained by Licensee."

As no Land Use Permit or a Quarry Permit was issued for work on Territorial Lands the above has put you in non-compliance, it is recommended that actions be taken to correct the non-compliance immediately.

Inspector's Signature: _____

INDUSTRIAL WATER USE INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2



INDUSTRIAL WATER USE INSPECTION REPORT

Figure 3
Source 174



Figure 4
174 refuel area

