



Telephone: 867-678-6676
Fax: 867-678-6699

March 24, 2017

Government of the Northwest Territories - Department of Transportation
PO Box 2038
Inuvik, NT X0E 0T0

Attention: Dean Ahmet

File Number N7L1-1835
Type of Operation CLASS A - INDUSTRIAL
Location KP61

Dear Dean Ahmet,

An inspection of the above noted operation was conducted on February 15, 2017 by Water Resources Officer Lloyd Gruben.

Enclosed is a copy of the INDUSTRIAL Water Use Inspection Report.
BLANK

If you have any questions, please contact me at 867-678-6676.

Sincerely,

Lloyd Gruben
Water Resources Officer
Environment and Natural Resources
Beaufort Delta

Cc:

Norman Snowshoe – A/Superintendent ENR Inuvik
Bijaya Adhikari – Science and Regulatory Coordinator, Inuvialuit Water Board
Mardy Semmler – Executive Director, Inuvialuit Water Board
Kevin C. Mcloed, Director, Highways and Marine, GNWT DOT
Doug Saunders – Operations Manager, E. Gruben's Transport Ltd.



«INSP_TYPE» WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1835	EXPIRY DATE:	December 11, 2023
LICENCEE:	Government of the Northwest Territories - Department of Transportation	PREVIOUS INSPECTION:	February 25, 2016
COMPANY REP:	Dean Ahmet	INSPECTION DATE:	February 15, 2017

WATER SUPPLY

Source:	KP61	Quantity Used:	N/A
Owner/Operator:	DOT	Meter Reading:	N/A

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Intake Facilities	N/A	Storage Structures	N/A	Treatment Systems	N/A	Recycling	N/A
Flow Meas. Device	N/A	Conveyance Lines	N/A	Pumping Stations	N/A	Chem. Storage	N/A
						Modifications	N/A

Water Supply Comments:

Approved Water Source KP61 was inspected - there was no activity/access road to KP61 at the time of the inspection. There were no environmental concerns to report.

WASTE DISPOSAL - SOLID WASTE

Disposal Method		Landfill					
Open Dump	N	Landfill	Y	Burn & Landfill	N	Underground	N
Offsite Removal	N	Other					



«INSP_TYPE» WATER USE INSPECTION REPORT

General Condition Comments:

On February 15, 2017, Water Resource Officer Lloyd Gruben inspected Water Licence N7L1-1835. The inspection included Trail Valley Creek, Hans Creek, Borrow Source 312 and Approved Water Source KP61.

MATTERS FOR FOLLOW UP

NON-COMPLIANCE/VIOLATIONS OF ACT OR LICENCE

No non-compliances were identified.

Inspector's Signature:

Date:	February 15, 2017	Licence #:	N7L1-1835	Page No:	3
-------	-------------------	------------	-----------	----------	---