



Telephone: 867-678-6676

Fax: 867-678-6699

March 9, 2017

Inuvialuit
Water Board

MAR 14 2017

Inuvik, NT

Government of the Northwest Territories - Department of Transportation
PO Box 2038
Inuvik, NT X0E 0T0

Attention: **Dean Ahmet, Senior Program Manager**

File Number N7L1-1835
Type of Operation CLASS A - INDUSTRIAL
Location

Dear Dean Ahmet,

An inspection of the above noted operation was conducted on March 02, 2017 by Water Resources Officer Lloyd Gruben. The inspection has 4 pages

During the inspection at borrow source 312, one non compliance was noted. No spill kit was visible at the fuel truck refill station.

If you have any questions, please contact me at 867-678-6676.

Sincerely,

Lloyd Gruben
Water Resources Officer
Environment and Natural Resources
Beaufort Delta

Cc:

Norman Snowshoe – Acting Superintendent, GNWT, ENR Inuvik Region

Mardy Semmler – Executive Director, Inuvialuit Water Board

Bijaya Adhikari – Science and Regulatory Coordinator, Inuvialuit Water Board

P O Box 2749, Inuvik, NT, X0E 0T0

«INSP_TYPE» WATER USE INSPECTION REPORT

Kevin Mcleod – Director, Highways & Marine, GNWT DOT
Doug Saunders – Operations Manager, E. Gruben’s Transport Ltd
Fred Bailey – Vice President, Northwind Industries
Alexis Campbell – Environment Analyst, DOT

Date:	March 02, 2017	Licence #:	N7L1-1835	Page No:	2
-------	----------------	------------	-----------	----------	---



«INSP_TYPE» WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1835	EXPIRY DATE:	December 11, 2023
LICENCEE:	Government of the Northwest Territories - Department of Transportation	PREVIOUS INSPECTION:	February 15, 2017
COMPANY REP:	Dean Ahmet	INSPECTION DATE:	March 02, 2017

FUEL STORAGE

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Owner:	EGTNW	Operator:	EGTNW	Condition of tanks:	
Berms & Liners		Water within Berm:		Evidence of Leaks:	

Drainage Pipes		Pump Station and Catchment Berm		Runoff Diversion	
Pipeline Condition					

Fuel Storage Comments:

An inspection was done on March 2, 2017 at Source 312. An inspection was done of the truck refueling station.



«INSP_TYPE» WATER USE INSPECTION REPORT

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

C &R Plan	N/I	Records & Reporting	A	Final Report	N/I
Geotechnical Inspection	N/I	Posting, Signage		Contingency Plan	N/I
Restorations Activities		Spills	A	O&M Plan	A
Maintenance	A	Modifications	N/I	Annual Report	N/I

General Condition Comments:

- On March 2, 2017, Water Resource Officer (Inspector) Lloyd Gruben and Manager of Wildlife & Environment Doug Villeneuve inspected the Inuvik to Tuktoyaktuk Highway to assess the Licensee's compliance with Water License N7L1 - 1835 (expiry December 11, 2023) and associated terms and conditions.

Weather was overcast with strong NW winds up to 50 KMs/hour. Temperature was -21

Trail Valley Creek Crossing (23A) Observations:

- Construction of bridge being done. Use of crane lifting and putting concrete in place for the bridge crossing.

Borrow Source 312 and Hans Creek Crossing Observation:

- Hans Creek Crossing, equipment working getting area ready for bridge construction.
- Did inspection of Borrow Source 312
- drip trays being utilized and area clean

NON-COMPLIANCE/VIOLATIONS OF ACT OR LICENCE

One non Compliance was observed. As per the Water License, no spill kit was observed at the truck refueling station



«INSP_TYPE» WATER USE INSPECTION REPORT

Inspector's Signature:



«INSP_TYPE» WATER USE INSPECTION REPORT

INSPECTION IMAGES