



Inuvialuit  
Water Board  
MAR 29 2017  
Inuvik, NT

Telephone: 867-678-6676  
Fax: 867-678-6699

March 27, 2017

Government of the Northwest Territories - Department of Transportation  
PO Box 2038  
Inuvik, NT X0E 0T0

Attention: Dean Ahmet

File Number                    N7L1-1835  
Type of Operation            CLASS A - INDUSTRIAL  
Location

Dear Dean Ahmet,

An inspection of the above noted operation was conducted on March 016, 2017 by Water Resources Officer Lloyd Gruben and Regional Environmental Protect Rolland Malegana.

Enclosed is a copy of the INDUSTRIAL Water Use Inspection Report. Report is three (3) pages

If you have any questions, please contact me at 867-678-6676.

Sincerely,

Lloyd Gruben  
Water Resources Officer  
Environment and Natural Resources  
Beaufort Delta

Cc:

Norman Snowshoe – A/Superintendent ENR, Inuvik  
Mardy Semmler – Executive Director – Inuvialuit Water Board  
Bijaya Adhikari – Science and Regulatory Coordinator, Inuvialuit Water Board  
Kevin C. Mcleod – Director, Highways and Marine , GNWT DOT  
Doug Saunders – Operations Manager, E. Gruben’s Transport Ltd.  
Fred Bailey – Vice President Northwind Industries  
Alexis Campbell – Environmental Analyst, DOT



**«INSP\_TYPE» WATER USE INSPECTION REPORT**

<b>LICENCE #:</b>	<b>N7L1-1835</b>	<b>EXPIRY DATE:</b>	<b>December 11, 2023</b>
<b>LICENCEE:</b>	<b>Government of the Northwest Territories - Department of Transportation</b>	<b>PREVIOUS INSPECTION:</b>	<b>February 15, 2017</b>
<b>COMPANY REP:</b>	<b>Dean Ahmet</b>	<b>INSPECTION DATE:</b>	<b>March 02, 2017</b>

**WASTE DISPOSAL - SEWAGE**

Disposal Method							
Mechanical	N	Camp Sump	N	Natural Water Body	N	Wetland Treatment	N
Continuous Discharge	N	Intermittent Discharge	N	Seasonal Discharge	N	Land Spread	N
Accelerated Biological	N	Other					

Indicate:    **A - Acceptable**        **U - Unacceptable**        **N/A - Not Applicable**    **N/I - Not Inspected**

Discharge Quality		Decant Process & Structures		Discharge Measurement Device	
Freeboard		Sludge Disposal Method			
Periods Of Discharge				SNP Samples Collected	
Effluent Discharge Rates					

**Sewage Comments:**

**FUEL STORAGE**

Indicate:    **A - Acceptable**        **U - Unacceptable**        **N/A - Not Applicable**    **N/I - Not Inspected**

Date:	March 02, 2017	Licence #:	N7L1-1835	Page No:	1
-------	----------------	------------	-----------	----------	---



**«INSP\_TYPE» WATER USE INSPECTION REPORT**

Owner:	EGTNW	Operator:	EGTNW	Condition of tanks:	A
Berms & Liners		Water within Berm:		Evidence of Leaks:	
Drainage Pipes		Pump Station and Catchment Berm	A	Runoff Diversion	
Pipeline Condition					

**Fuel Storage Comments:**

An inspection was done on March 16, 2017 at Source 312. An inspection was done of the truck refueling station, everything clean and in good standing

**GENERAL CONDITIONS/REPORTS/PLANS**

Indicate:    **A - Acceptable**        **U - Unacceptable**        **N/A - Not Applicable**    **N/I - Not Inspected**

C &R Plan	N/I	Records & Reporting	A	Final Report	N/I
Geotechnical Inspection	N/I	Posting, Signage		Contingency Plan	N/I
Restorations Activities		Spills	A	O&M Plan	A
Maintenance	A	Modifications	N/I	Annual Report	N/I

**General Condition Comments:**

On March 16, 2017, ENR Inspectors, Lloyd Gruben, WRO and Rolland Malegana conducted a ITH inspection.

Weather that day was clear and sunny with -21 temperature

At approx. 1:50 pm, we checked in with Northwind Industries that we will be conducting ITH inspection

At Approx 2:00 pm, We entered the South end of ITH to do the ITH inspection.

We arrived at Trail Valley Creek crossing, concrete slabs was put in place for the bridge but work still has to be done for the approaches. Everything in good standing



### «INSP\_TYPE» WATER USE INSPECTION REPORT

At 2:50 we arrived at Hans Creek crossing, work being done to get the concrete slabs installed for the bridge

We then made our way to Source 312, checked at refueling station, everything in good standing. We then went toward the camp and noticed that camp up and running. Inspected camp area, everything in good order. Drip trays being utilized. We stopped and talked with ILA environmental Monitor, Mary Cockney. Asked if any problems, her response was everything good with the camp and work being done.

#### NON-COMPLIANCE/VIOLATIONS OF ACT OR LICENCE

Inspector's Signature:



## «INSP\_TYPE» WATER USE INSPECTION REPORT

### INSPECTION IMAGES

Date:	March 02, 2017	Licence #:	N7L1-1835	Page No:	4
-------	----------------	------------	-----------	----------	---