



1	File
1	W. RES.
1	E.A.
1	G.W.
1	8
COPY	

INDIAN AND NORTHERN AFFAIRS - CANADA
N.W.T. REGION
OCT 02 1995
WATER RESOURCES DIVISION
YELLOWKNIFE, NT


MUNICIPAL WATER USE INSPECTION FORM

DATE: September 18, 1995 COMPANY REP.: Pete Noyes
 LICENSEE: Hamlet of Tuktoyaktuk LICENCE #: N7L3-0714

WATER SUPPLY

Source (s): Kudlak Lake Quantity Used (to date): unknown, refer to the report.
 Owner/Operator: Hamlet (estimate or actual)

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable
 Intake Facilities: U Storage Structure A Treatment Systems A Chem. Storage A
 Flow Meas. Device A Convey. Lines A Pumping Stations A
 Comments: no screen on intake at Kudlak lake.



WASTE DISPOSAL

Sewage Treatment System (primary, secondary or tertiary) primary
 Natural Water body Continuous Discharge (land or water) Yes
 Seasonal Discharge Wetlands Treatment No Trench Yes, 30m
 Solid Waste: Owner/Operator: Hamlet
 Landfill Burn & Landfill _____ Other _____

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable
 Disch. Quality A Decant Structure N/A - pumping operation Erosion A
 Disch. Meas. Dev. A Dyke Inspection by inspector only Seepages N/A
 Dams, Dykes U Freeboard U Spills N/A none reported
 Construction N/A O & M Plan due Jan. 15/96 A & R Plan N/A
 Periods of Discharge: A Effluent Discharge Rate: _____
 Comments: dyke at sewage lagoon had less than 0.5 meters freeboard
poor segregation at dump.
Heavy bag pit not acceptable.

FUEL STORAGE

Owner: N/A Operator _____ Condition of Tanks _____
 Berms & Liners _____ Water within berm: _____ Evidence of Leaks: _____
 Drainage Pipes _____ Pump Station and Catchment Berm _____
 Pipeline Condition _____ Not Applicable: _____

SURVEILLANCE NETWORK PROGRAM

Samples Collected: (Hamlet) at SNP 0714-2; prior to decant
 (DIAND) at SNP 0714-1, 0714-2, and 0714-3; during inspection
 Signs Posted: SNP water observation only (ie. 0714-1) Warning NO
 Record & Reporting Satisfactory

Geotechnical Inspection: N/A - ie. not required
 Non-Compliance of Act or Licence: Posting requirements still not met.
Hamlet has not complied with SNP item B.2; that is, sampling at SNP 0714-3 not done yet.

Page 2 attached Yes _____ No X
 Licensee Representatives Title: F. REINAN Inspectors Name: Scott Gullidge
 Licensee Representatives Signature: _____ Inspectors Signature: _____